

### Legend

- Remove existing 3 strand T post fence/replace with new 6' chain link fencing and signage
- - - - - New 6' chain link fencing and signage
- New 6' Man Gate
- New 20' Double Wide Swing Gate
- Inspect condition of existing fencing and signage-repair/amend as necessary

- Estimated Extent of Radiologically Impacted Material
- - - - - Property Line
- Index Contour 10' Interval
- Intermediate contour 2' Interval




Figure 2  
Fencing Plan with  
2-foot Contour Intervals  
(revised 5-20-13)

West Lake Landfill Operable Unit-1

EMSI Engineering Management Support, Inc.